



1/13
FIG.1




2/13
FIG.2




3/13

FIG.3



4/13
FIG.4



5/13

FIG.5

AXIS DEVIATION RELATIVE TO OBJECTIVE LENS EXCEED TOLERANCE
LEVEL. DO YOU EXECUTE AXIS ALIGNMENT ?

Yes

No

FIG.6




FIG.7




FIG.8 (a)




FIG.8 (b)




FIG.9






FIG.10



11/13
FIG.11



12/13
FIG.12

(500)

(501) ☒ Auto Focus

(502) ☒ Alignment Pattern

(503) ☐ Wafer Pattern

(504) Axis

(505) Mag. (30k~100k)

(506) Frame

Auto Axis Alignment (511b) (511c)

(511a) Mode ☐ 1 ☒ 2 ☐ 3

(507) ☒ Auto Stigma Alignment X

(508) ☒ Auto Stigma Alignment Y

(509) ☒ Auto Axis Alignment

(510) ☒ Auto Stigma

13/13
FIG.13

